

CREATING SAFETY IN WELDING OPERATIONS (Concise)
REVIEW QUIZ

Name _____ Date _____

Please provide answers to the following to show how well you understand the information presented during this program.

1. Welding jobs that must be performed on objects outside the designated area require a hot work permit.
 - a. true
 - b. false

2. Prior to a hot work operation, all ignitable debris within a _____ radius of the worksite should be swept up.
 - a. 10 feet
 - b. 15 feet
 - c. 35 feet

3. High-top leather safety boots offer the best foot protection while welding.
 - a. true
 - b. false

4. Most welding gloves are effective in preventing burns when handling extremely hot materials.
 - a. true
 - b. false

5. Safety glasses with side shields should always be worn under your welding helmet.
 - a. true
 - b. false

6. Part of good housekeeping is returning supplies and equipment to their proper storage area when the job is complete.
 - a. true
 - b. false

7. You only need to make sure you have adequate ventilation when welding in confined areas where fumes may accumulate.
 - a. true
 - b. false

8. When working in tight quarters, you should work and move a little _____ than normal.
 - a. faster
 - b. slower

9. Before using the welding machine, you should make sure it is properly grounded and in good working order.
 - a. true
 - b. false

ANSWERS TO THE REVIEW QUESTIONS

1. a

2. c

3. a

4. b

5. a

6. a

7. b

8. b

9. a